

Annex A


CFL bulb that failed the Mercury test - “OSRAM Daylight”



Test Results for Mercury test

Test No.	Tested measurement of Mercury content (mg/tube)	Maximum Mercury limits for CFLs (mg/tube)	Conformness to requirements	Remarks
1	13.8	5	No	CFL exceeded maximum mercury limits by 2.76 times.
2	23.9	5	No	CFL exceeded maximum mercury limits by 4.78 times.

CFL bulb that failed the luminous flux measurement test - “PowerPac Energy Saving Bulb”



Test Results for Luminous Flux Measurement Test

Test No.	Specifications Lumens (lm)	Actual Lumens (lm)	Specification Watts (W)	Actual Watts (W)	Remarks
1	650	255	13	7.5	Results for Lumens is 2.5

					times lower than specified, and Watts 1.7 times lower than stated.
2	650	243	13	7.5	Results for Lumens is 2.67 times lower than specified, and Watts 1.7 times lower than stated